- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire

# survey report on:

Property address	Flat 1 7 Magdala Crescent Edinburgh EH12 5BE
Customer	Mr & Mrs P Burbridge
Customer address	c/o HBJ Gateley 19 Canning Street Edinburgh EH3 8HE
Prepared by	J & E Shepherd
Date of inspection	6th January 2015



Tel. 0845 263 7995 www.shepherd.co.uk

#### **PART 1 - GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller:
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report <sup>2</sup> will be from information contained in the Report and the generic Mortgage Valuation Report.

 $<sup>^2</sup>$ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of
  valuation between a willing buyer and a willing seller in an arm's-length transaction after proper
  marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member
  or partner (unless the Surveyor is not an employee, director, member or partner, when the
  "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1. <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

#### WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions:
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subject property comprises a converted ground floor flat within a three storey block.
Accommodation	Ground Floor: Entrance hallway, living room, bedroom, kitchen and bathroom with wc.
Gross internal floor area (m²)	69 square metres or thereby.
Neighbourhood and location	The subjects are situated in an established residential area of mixed style properties lying to the West of Edinburgh City Centre and convenient for local shopping, educational and social facilities.
Age	1880 approx having been converted circa 8 years ago.
Weather	Dry and sunny.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.  Masonry with clay pots.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.  Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.  Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.  If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.

	The roof would appear multi pitched and slated with flat platform present, however, only a heavily restricted inspection took place from street level.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Cast iron gutters and downpipes with parapet gutter to the front elevation.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of traditional 600mm solid stone work pointed externally.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows throughout are of a timber sash and casement single glazed type with a UPVC double glazed sash and casement style within the kitchen. The front access door is of a timber variety.
	The windows within the living room and the bedroom have been draft proofed. Any documentation regarding this should be sought.
External decorations	Visually inspected.
	Painted timber and UPVC finishes.
Conservatories / porches	None.
Communal areas	Circulation areas visually inspected.
	There is a communal entrance hall and stairwell.
Garages and permanent outbuildings	None
Outside areas and boundaries	Visually inspected.
	The property benefits from private garden ground to the front elevation. The boundaries are defined by masonry walls and cast iron railings.
	The subject property benefits from access to the shared garden ground immediately across the road. We understand there is an annual maintenance fee for the upkeep of this area.

#### skraineserrak


Ceilings	Visually inspected from floor level.
	Presumed plasterboard and plaster finish ceilings.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls have plaster finishes.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	The floors throughout are of suspended timber variety and solid concrete construction. No access was afforded to any sub floor areas.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
•	Kitchen units were visually inspected excluding appliances.
	The kitchen fittings are of a wall and base type with worktop surface areas present. The internal doors, skirtings and facings are of a timber variety.
Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	There is a coal effect gas stove in the living room.
Internal decorations	Visually inspected.
	Painted throughout.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply with the fusebox located in the entrance hallway.

Accessible parts of the system were visually inspected withou removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
Mains supply with gas meter located in entrance hallway.
Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
No tests whatsoever were carried out to the system or appliances.
Water is from the mains supply. The plumbing where seen is of copper supply pipes and PVC waste pipes. The sanitary fittings comprise a three piece suite in the bathroom.
Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
No tests whatsoever were carried out to the system or appliances.
The property benefits from a gas fired central heating system with the gas combination boiler located in the kitchen.
Drainage covers etc. were not lifted.
Neither drains nor drainage systems were tested.
Presumed to main public sewer.
Visually inspected.
No tests whatsoever were carried out to the system or appliances.
The property benefits from smoke alarms.
For flats / maisonettes
Only the subject flat and internal communal areas giving access to the flat were inspected.
If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The property was fully floor covered and furnished at the time of inspection. The cupboards were full of possessions at the time of inspection. No access was afforded beneath the sanitary fittings. No access was afforded to any sub floor areas. No access was afforded into the roof void area or onto the flat roof platform due to the lack of an access hatch within the communal stairwell. No access was afforded to the rear elevation due to the lack of access. The chimneys and the roof decks were partially viewed from ground floor level only, however, the parapet gutters and the flat roof platform could not be inspected. The services were not tested.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.

# Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- (1) Chimney pots
- (2) Coping stone
- (3) Chimney head
- (4) Flashing
- (5) Ridge ventilation
- Ridge board
- (7) Slates/tiles
- (8) Valley guttering
- (9) Dormer projection
- 10 Dormer flashing
- (11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- (15) Collar
- (16) Insulation
- (17) Parapet gutter
- (8) Eaves guttering
- (19) Rainwater downpipe
- (20) Verne boards /skews
- (21) Soffit boards
- (22) Partition wall
- (23) Lath/plaster
- (24) Chimney breast
- 25) Window pointing
- (26) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- (29) Bay window projection
- (30) Lintels
- (31) Cavity walls / wall ties
- (32) Subfloor ventilator
- (3) Damp proof course
- (34) Base course
- (35) Foundations
- (36) Solum
- 37 Floor joists
- (38) Floorboards:
- (39) Water tank
- (0) Hot water tank

# 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	The subject property has suffered from previous structural movement however this appears to be of a longstanding and non progressive nature given the limitations of our single survey.

Dampness, rot and infestation		
Repair category	1	
Notes	No dampness was noted at the time of inspection, however, not all walls could be tested due to the presence of furniture and possessions.	

Chimney stacks	
Repair category	1
Notes	From our limited street level inspection the chimney stacks appeared in satisfactory condition, however, it should be noted not all areas of the chimneys could be seen. Due to the age and type of construction ongoing maintenance to the chimneys and the flashings should be anticipated in accordance with good maintenance practice.

Roofing including roof space	
Repair category	2
Notes	The flat roof platform will have higher than average maintenance costs and a limited life span and ongoing maintenance to this area should be anticipated. Slipped and cracked slates noted. A heavily restricted inspection of the roof decks was carried out from street level only. No inspection of the flat roof platform took place due to the lack of access from the communal stairwell.



Rainwater fittings	
Repair category	2
Notes	We recommend the parapet gutters be cleared and maintained on a regular basis. No inspection of the parapet gutters took place.  Corrosion noted to the cast iron downpipes.  We recommend the rainwater goods be monitored under a heavy downpour to ensure they are free of defects with any necessary remedial works being carried out thereafter.

Main walls	
Repair category	1
Notes	Minor weathering noted to the timber windows. Ongoing maintenance should be anticipated.

Windows, external doors and joinery	
Repair category	
Notes	We recommend a precautionary check of all windows and doors prior to purchase.

External decoration	s
Repair category	1
Notes	Ongoing maintenance to the external timberwork should be anticipated.

Conservatories/por	ches
Repair category	-
Notes	None.

Repair category	1
Notes	Plaster defects noted in the communal stairwell. Cracked glazing noted to the cupola at the stairhead within the communal stair.

Garages and permanent outbuildings	
Repair category	-
Notes	None.

Outside areas and boundaries	
Repair category	1
Notes	Ongoing maintenance to the masonry wall to the front elevation should be anticipated.

Ceilings	
Repair category	1
Notes	Minor plaster cracking noted.

Internal walls	
Repair category	1
Notes	Minor plaster cracking noted.

Floors including sub-floors	
Repair category	1
Notes	Loose floorboards noted. No access was afforded to any sub floor areas.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No serious defects noted.

Chimney breasts and fireplaces	
Repair category	1
Notes	We presume all chimney breasts, fireplaces and flues will be checked and cleared prior to use.

Internal decorations	
Repair category	1
Notes	No serious defects noted.

Cellars	
Repair category	-
Notes	None.

Electricity	
Repair category	1
Notes	The Institute of Engineering and Technology recommends that inspection and testings are undertaken at least every 10 years and on a change of occupancy. It should be appreciated that only the most recently constructed or rewired properties will have installations which fully comply with present IET Regulations.

(as	
Repair category	1
Notes	We presume the gas supply is free of defects.

Water, plumbing and bathroom fittings				
Repair category	1			
Notes	No access was afforded beneath the sanitary fittings. We presume the sealants and tiling around the sanitary fittings are fully functional and no defects are present to adjacent areas, however, due to the lack of inspection it may be prudent to have this area checked prior to purchase.			
	Due to the age of the property it is possible that lead plumbing exists. If this is the case we recommend it be removed.			

Heating and hot water				
Repair category	1			
Notes	We presume the gas fired central heating system and hot water system have been checked and serviced by a Gas Safe Engineer and currently comply with regulations.			

# Repair category 1 Notes The drainage system has not been tested however we presume this is free of defects.

# istranismašinas

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	2
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	1
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

#### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground	
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X	
3. Is there a lift to the main entrance door of the property?	Yes No X	
4. Are all door openings greater than 750mm?	Yes No X	
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No	
6. Is there a toilet on the same level as a bedroom?	Yes X No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No	
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No	

# istrate strate

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The subject property has been converted circa 8 years ago to form the present layout and accommodation and we presume the necessary consents and permissions were obtained at the time with documentation held safe with the Title Deeds.

A replacement UPVC double glazed sash and casement style window have been installed in the kitchen.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialists or contractors advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

#### Estimated reinstatement cost for insurance purposes

We are of the opinion that the present re-instatement value of the property with due allowance for demolition, site clearance and professional fees would be fairly stated in the region of £220,000 (Two Hundred and Twenty Thousand Pounds Sterling).

#### Valuation and market comments

In forming our valuation due consideration has been given to the condition and situation of the property together with the likely demand for a property of this size and nature in this area. We are therefore of the opinion that the current market value, with the benefit of vacant possession may be fairly stated in the region of £275,000 (Two Hundred and Seventy Five Thousand Pounds Sterling).

Market conditions are steady at the present time.

Signed	Security Print Code [481353 = 2268 ] Electronically signed
Report author	Christopher Hunter
Company name	J & E Shepherd
Address	12 Atholl Crescent, Edinburgh, EH3 8HA
Date of report	8th January 2015



Tel: 0845-263 7995 www.shepherd.co.uk

Property Address						
Address Seller's Name Date of Inspection	Flat 1, 7 Magdala Mr & Mrs P Burbi 6th January 2015	•	urgh, EH12 5BE			
Property Details						
Property Type	☐ House ☐ Purpose built flat	Bungalow  X Converted flat	Purpose built maiso	Flat over	d maisonette non-residential use ecify in General Remark	s)
Property Style	Detached Back to back	Semi detached High rise block	Mid terrace X Low rise block	End terral	ce ecify in General Remark	s)
Does the surveyor bel e.g. local authority, mi	lieve that the propilitary, police?	erty was built for	the public sector,	Yes	X No	
Flats/Maisonettes only Approximate Year of 0	y Floor(s) on which		No. of floors in block	= '	Yes X No	
Tenure						
X Absolute Ownership	Leasehold	Ground rent £	Unexpir	red years	<u> BRANGERERAN AGIN AGIN BUR</u>	ding
Accommodation						
Number of Rooms	1 Living room(s) 1 Bathroom(s)	1 Bedroom(s) 0 WC(s)	1 Kitchen(s) 0 Other (Specify in C	General remarks)	THE STATE OF THE S	Allen .
Gross Floor Area (exc Residential Element (g			69 m² (Internal)	m² (External)	A THE CONTRACT OF THE CONTRACT	
Garage / Parking / C Single garage Available on site?	Outbuildings  Double garage  Yes No	Parkiı	ing space	X No garage / garaç	ge space / parking space	
Permanent outbuilding	js:					
None.						

Construction							
Walls	Brick	X Stone	Concrete	Timber frame	Othe	r (specify in Gen	eral Remarks)
Roof	Tile	X Slate	Asphalt	Felt	Othe	r (specify in Gen	eral Remarks)
Special Risks							
Has the property suff	fered structur	ral movement?	)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$7\$ 31\$ 242-31\$ -245-31\$ 275-21\$ \$1	X Yes	∏ No
If Yes, is this recent of	or progressiv	e?				Yes	X No
Is there evidence, his immediate vicinity?	story, or reas	on to anticipat	e subsidence,	heave, landslip o	or flood in the	e Yes	X No
If Yes to any of the a	bove, provide	e details in Ge	neral Remarks				
		sácics agus at this sa		32 S0522 (1945) 844 (195 <u>4)</u>			1, 15 da again (5 da 1841 1841)
Service Connectio	ns						
Based on visual insport the supply in General			appear to be	non-mains, pleas	se comment	on the type a	nd location
Drainage X	Mains	Private	None	Water	X Mains	Private	None
Electricity	Mains	Private	None	Gas	X Mains	Private	None
Central Heating X	Yes	Partial	None				
Brief description of C	entral Heatin	ng:					
Gas fired to steel pa	anel radiators			or and beautic The Control of The Control on the Control			
Site Apparent legal issues	s to be verific	ed by the conv	eyancer. Pleas	se provide a brief	f description	in General R	emarks.
	Shared drives			menities on separate	[]	red service conn	
Ill-defined boundaries	-	_	land included with	•	_	er (specify in Ger	neral Remarks)
Location							
Residential suburb	X Reside	ential within town /	city Mixed	residential / commer	cial 🔲 Main	ily commercial	
Commuter village	Remot	te village	Isolate	ed rural property	Othe	er (specify in Ger	neral Remarks)
Planning Issues Has the property bee	en extended /	converted / al	tered? X Ye	es No			
If Yes provide details				_			
Roads							

General Remarks	
	ca 8 years ago to form the present layout and accommodation and rmissions were obtained at the time with documentation held safe
Replacement UPVC double glazed sash and	d casement style windows have been installed in the kitchen.
At the time of inspection the general condition construction.	on of the property appears consistent with its age and type of
The subject property has suffered from previous longstanding and non progressive nature give	ous structural movement however this appears to be of a ren the limitations of our single survey.
Ongoing maintenance to the external fabric and the parapet gutters, at which it should be	of the building should be anticipated in particular the flat roof platform e noted that these areas were not inspected.
Essential Repairs	
None.	
Estimated cost of essential repairs £	Retention recommended? Tyes No Amount f

Comment on Mortgagea	bility	
We consider the subjects	offer suitable security for mortgage purposes.	
Valuations  Market value in present cor Market value on completior Insurance reinstatement va (to include the cost of total Is a reinspection necessary	n of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 275,000 £ 220,000
Buy To Let Cases		
What is the reasonable rangementh Short Assured Tena	ge of monthly rental income for the property assuming a letting on a 6	£ 750-850
	here there is a steady demand for rented accommodation of this type?	X Yes No
<b>Declaration</b>		
Signed	Security Print Code [481353 = 2268 ] Electronically signed by:-	TAX
Surveyor's name	Christopher Hunter	
Professional qualifications Company name	MA (Hons) MRICS J & E Shepherd	
Address	12 Atholl Crescent, Edinburgh, EH3 8HA	
Telephone	0131 225 1234	
Fax	0131 220 3178	
Report date	8th January 2015	

# Energy Performance Certificate (EPC)



#### FLAT 1, 7 MAGDALA CRESCENT, EDINBURGH, EH12 5BE

Dwelling type: Ground-floor flat
Date of assessment: 06 January 2015
Date of certificate: 07 January 2015

Total floor area: 69 m<sup>2</sup>

Reference number: Type of assessment: Primary Energy Indicator: Main heating and fuel: 3815-7229-1000-0456-7906 RdSAP, existing dwelling 374 kWh/m²/year

Boiler and radiators, mains


gas

You can use this document to:

- · Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- · Find out how to save energy and money and also reduce CO2 emissions by improving your home

Estimated energy costs for your home for 3 years* £3,138	interesse your life in
Over 3 years you could save* £1,350	ragion (of more information

<sup>\*</sup> based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



The charge amount inglier falling cools	L	L
Very environmentally friendly - lower CO <sub>2</sub> emissions	Current	Potential
(92 plus) 🔊		
(81.91) B		
(69-80) C	<b>(42</b> ]	ିନ୍ଦ୍ର
(65:66)		
(39:34		
(4)-20)		
Not environmentally friendly - higher CO <sub>2</sub> emissions	<u> </u>	

# Energy Efficiency Remo

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Based on calculated energy use of 374 kWh/m²/yr, your current rating is band E (54). The average rating for a home in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

# Environmental Impact (00g) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Based on calculated emissions of 5 kg CO2/m²/yr, your current rating is band E (42). The average rating for a home in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

# Roparetions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Internal or external wall insulation	£4,000 - £14,000	£726	0
2 Floor insulation (suspended floor)	£800 - £1,200	£255	<b>Q</b>
3 Low energy lighting	£15	£84	

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details:

THIS RACE IS THE ENERGY REAFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED WHILES IT IS REPLACED WITH ANUISDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	***	***
	Solid brick, as built, no insulation (assumed)	***	$\star\star$
Roof	(another dwelling above)	<u>—</u>	
Floor	Suspended, no insulation (assumed)	<u>—</u>	
Windows	Single glazed	***	***
Main heating	Boiler and radiators, mains gas	<b>★★★★☆</b>	****
Main heating controls	TRVs and bypass	****	***
Secondary heating	Room heaters, coal		
Hot water	From main system	<b>★★★★☆</b>	<b>★★★</b> ☆
Lighting	Low energy lighting in 25% of fixed outlets	****	***

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

# The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.4 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.7 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

#### Estimated energy costs for this home

No.	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,598 over 3 years	£1,347 over 3 years	
Hot water	£297 over 3 years	£300 over 3 years	Yourgould
Lighting	£243 over 3 years	£141 over 3 years	save £1 350
Totals	£3,138	£1,788	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Re	commended measures	Indicative cost	Typical saving per year	Rating after Energy	improvement Environment	i Grana Na Garia
1	Internal or external wall insulation	£4,000 - £14,000	£242	D 64	<b>€</b> D 56	0
2	Floor insulation (suspended floor)	£800 - £1,200	£85	D 68	<b>∢</b> D 62	0
3	Low energy lighting for all fixed outlets	£15	£28	(C 69	<b>€D 63</b>	
4	Upgrade heating controls	£350 - £450	£24	⟨C 70	<b>€</b> D.64	8
5	Replace single glazed windows with low-E double glazed windows	£3,300 - £6,500	£71	⟨C 73	<b>۩ 69</b>	<b>(2</b> )

Measures which have a green deal tick are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

#### Choosing the deht improvement eackage

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that planning permission might be required and that building regulations apply to this work so it is best to check with your local authority whether a building warrant or planning permission will be required.

#### 2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

#### 3 Low energy lighting

Replacement of traditional light bulbs with energy saving recommended ones will reduce lighting costs over the lifetime of the bulb, and they last up to 12 times longer than ordinary light bulbs. Also consider selecting low energy light fittings when redecorating; contact the Lighting Association for your nearest stockist of Domestic Energy Efficient Lighting Scheme fittings.

#### 4 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a qualified heating engineer.

#### 5 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

# Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	12,568	N/A	N/A	(4,193)
Water heating (kWh per year)	1,989			

# Addematum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

#### About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Christopher Hunter

Assessor membership number: EES/016138 Company name/trading name: J & E Shepherd Address: 13 Albert Square

Dundee DD1 1XA

Phone number: 01382 200454 Email address:

c.hunter@shepherd.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

This Certificate and Recommendations Report will be available to view online by any party with access to the report reference number (RRN) and to organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK Governments. If you are the current owner or occupier of this building and do not wish this data to be used by these organisations to contact you in relation to such initiatives, please opt out by visiting www.scottishepcregister.org.uk and your data will be restricted accordingly. Further information on this and on Energy Performance Certificates in general can be found at www.scotland.gov.uk/epc.

# Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.

Authorised home energy assessment

Finance at no upfront cost

Choose from authorised installers

May be paid from savings in energy bills Repayments stay with the electricity bill payer

# **Property Questionnaire**

Property Address	7 Magdala Crescent
	Edinburgh
	EH12 5BE

Seller(s)	Mr and Mrs P Burbridge

Completion date of property questionnaire	12/01/2015
---	------------

1	Length of ownership How long have you owned the property? 7 years
2	Council tax Which Council Tax band is your property in? D
3	Parking   What are the arrangements for parking at your property?   (Please tick all that apply)   Garage   □   Allocated parking space □   Driveway □   Shared parking □   On street ✓   Resident permit □   Metered parking □   Other (please specify)
4	Conservation area Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)? Yes
5	Listed buildings Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)? Yes
<b>6</b> a.(i)	Alterations/additions/extensions  During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?  No  If you have answered yes, please describe below the changes which you have made:
(ii)	Did you obtain planning permission, building warrant, completion certificate and other consents for this work?  No  If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.  If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:
	Planing permission and building warrants were arranged by the previous owner who

undertook the flat renovation. We do not have copies. Work

b.

property?

Have you had replacement windows, doors, patio doors or double glazing installed in your

No

If you have answered yes, please answer the three questions below:

- (i) Were the replacements the same shape and type as the ones you replaced?
- (ii) Did this work involve any changes to the window or door openings?
- (iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):

Please give any guarantees which you received for this work to your solicitor or estate agent.

#### 7 Central heating

a. Is there a central heating system in your property?

(Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).

Yes

If you have answered yes or partial — what kind of central heating is there?

(Examples: gas-fired, solid fuel, electric storage heating, gas warm air).

Full, gas-fired with radiators throughout the flat.

If you have answered yes, please answer the three questions below:

- (i) When was your central heating system or partial central heating system installed? some 8 years ago
- (ii) Do you have a maintenance contract for the central heating system?

If you have answered yes, please give details of the company with which you have a maintenance contract:

Scottish Gas

(iii) When was your maintenance agreement last renewed?

(Please provide the month and year).

10/2014

# 8 Energy Performance Certificate

Does your property have an Energy Performance Certificate which is less than 10 years old?

No

## 9 Issues that may have affected your property

a. Has there been any storm, flood, fire or other structural damage to your property while you have owned it?

No

If you have answered yes, is the damage the subject of any outstanding insurance claim?

b. Are you aware of the existence of asbestos in your property?

No

If you have answered yes, please give details:

#### 10 Services

Please tick which services are connected to your property and give details of the supplier: Services **Connected Supplier** Gas or liquid petroleum gas  $\square$ Scottish gas Edinburgh Corporation/ Scottish Water mains or private water supply  $\square$ water Electricity SSE M Mains drainage  $\mathbf{\Lambda}$ Edinburgh Council Telephone  $\square$ BT Cable TV or satellite П Optical cable into property. Not Broadband  $\mathbf{V}$ connected at this moment. b. Is there a septic tank system at your property? No Do you have appropriate consents for the discharge from your septic tank? (i)

(ii) Do you have a maintenance contract for your septic tank?

If you have answered yes, please give details of the company with which you have a maintenance contract:

## 11 Responsibilities for shared or common areas

a. Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? Yes

If you have answered yes, please give details:

cleaning of hallway and front steps.

b. Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?

Yes

If you have answered yes, please give details:

There is a joint responsibility for common repairs.

c. Has there been any major repair or replacement of any part of the roof during the time you have owned the property?

No

d. Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?

Yes

If you have answered yes, please give details:

access to rear of property for maintenance.

e. As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?

No

If you have answered yes, please give details:

f. As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the

land is privately-owned.)

No

If you have answered yes, please give details:

# 12 Charges associated with your property

a. Is there a factor or property manager for your property?

b. Is there a common buildings insurance policy?

No

If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?

c. Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.

Annual payment of £0 for maintenance of the shared gardens in Mandala Crescent.

## 13 Specialist works

a. As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?

No

If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.

b. As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?

No

If you have answered yes, please give details:

We believe that damp proofing was carried out when the flat was refurbished.

c. If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?

If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate., these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.

Guarantees are held by:

#### 14 Guarantees

- a. Are there any guarantees or warranties for any of the following:
- (i) Electrical work

Don't know

- (ii) Roofing Don't know
- (iii) Central heating Don't know
- (iv) National House Building Council (NHBC)

  Don't know
- (v) Damp course Don't know
- (vi) Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)
  Don't know
- b. If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):
- (i) Electrical work
- (ii) Roofing
- (iii) Central heating
- (iv) National House Building Council (NHBC)
- (v) Damp course
- (vi) Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)
- c. Are there any outstanding claims under any of the guarantees listed above?

If you have answered yes, please give details:

#### 15 Boundaries

So far as your are aware, has any boundary of your property been moved in the last 10 years?

No

If you have answered yes, please give details:

# 16 Notices that affect your property

In the past three years have you ever received a notice:

- a. advising that the owner of a neighbouring property has made a planning application?
   No
- that affects your property in some other way?
   No
- c. that requires you to do any maintenance, repairs or improvements to your property?

If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the

purchaser of your property.