



# HOME REPORT



PROVIDING HOME REPORTS AT A TIME THAT SUITS YOU

[WWW.HOMEREPORTCOMPANY.CO.UK](http://WWW.HOMEREPORTCOMPANY.CO.UK)



# ENERGY PERFORMANCE CERTIFICATE



PROVIDING HOME REPORTS AT A TIME THAT SUITS YOU

[WWW.HOMEREPORTCOMPANY.CO.UK](http://WWW.HOMEREPORTCOMPANY.CO.UK)

# Energy Performance Certificate (EPC)

# Scotland

Dwellings

FLAT 3/2 , 91 BARLOGAN AVENUE, GLASGOW, G52 1AG

**Dwelling type:** Top-floor flat  
**Date of assessment:** 24 May 2018  
**Date of certificate:** 29 May 2018  
**Total floor area:** 40 m<sup>2</sup>  
**Primary Energy Indicator:** 306 kWh/m<sup>2</sup>/year


**Reference number:** 2045-1008-7205-4128-9904  
**Type of assessment:** RdSAP, existing dwelling  
**Approved Organisation:** Elmhurst  
**Main heating and fuel:** Boiler and radiators, mains gas

## You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

|  |               |  |
|--|---------------|--|
| <b>Estimated energy costs for your home for 3 years*</b> | <b>£1,551</b> | See your recommendations report for more information |
| <b>Over 3 years you could save*</b>                      | <b>£594</b>   |  |

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




## Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (67)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (67)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

| Recommended measures                   | Indicative cost  | Typical savings over 3 years | Available with Green Deal |
|--|------------------|------------------------------|---------------------------|
| 1 Internal or external wall insulation | £4,000 - £14,000 | £327.00                      | ✓                         |
| 2 Low energy lighting                  | £10              | £39.00                       |                           |
| 3 Condensing boiler                    | £2,200 - £3,000  | £87.00                       | ✓                         |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

**THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description   | Energy Efficiency | Environmental |
|-----------------------|---|-------------------|---------------|
| Walls                 | Sandstone or limestone, as built, no insulation (assumed) | ★☆☆☆☆             | ★☆☆☆☆         |
| Roof                  | Pitched, 150 mm loft insulation                           | ★★★★☆             | ★★★★☆         |
| Floor                 | (another dwelling below)                                  | —                 | —             |
| Windows               | Single glazed   | ★☆☆☆☆             | ★☆☆☆☆         |
| Main heating          | Boiler and radiators, mains gas                           | ★★★★☆             | ★★★★☆         |
| Main heating controls | Programmer, room thermostat and TRVs                      | ★★★★☆             | ★★★★☆         |
| Secondary heating     | None  | —                 | —             |
| Hot water             | From main system  | ★★★★☆             | ★★★★☆         |
| Lighting              | Low energy lighting in 50% of fixed outlets               | ★★★★☆             | ★★★★☆         |

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.


## The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 54 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.2 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.1 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

## Estimated energy costs for this home

|               | Current energy costs | Potential energy costs | Potential future savings  |
|---------------|----------------------|------------------------|---|
| Heating       | £1,164 over 3 years  | £642 over 3 years      |  |
| Hot water     | £249 over 3 years    | £222 over 3 years      |   |
| Lighting      | £138 over 3 years    | £93 over 3 years       |   |
| <b>Totals</b> | <b>£1,551</b>        | <b>£957</b>            |   |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures   | Indicative cost  | Typical saving per year | Rating after improvement |             | Green Deal |
|--|------------------|-------------------------|--------------------------|-------------|------------|
|  |                  |                         | Energy                   | Environment |            |
| 1 Internal or external wall insulation                           | £4,000 - £14,000 | £109                    | C 73                     | C 76        | ✓          |
| 2 Low energy lighting for all fixed outlets                      | £10              | £13                     | C 74                     | C 76        |            |
| 3 Replace boiler with new condensing boiler                      | £2,200 - £3,000  | £29                     | C 76                     | C 79        | ✓          |
| 4 Replace single glazed windows with low-E double glazed windows | £3,300 - £6,500  | £47                     | C 78                     | B 83        | ✓          |

Measures which have a green deal tick ✓ are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick ✓ may need additional finance. To find out how you could use Green Deal finance to improve your property, visit [www.greenerscotland.org](http://www.greenerscotland.org) or contact the Home Energy Scotland hotline on 0808 808 2282.

### Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)

## Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to [www.greenerscotland.org](http://www.greenerscotland.org).

## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### 1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

### 2 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (<http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting>).

### 3 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

### 4 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

## Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to [www.energysavingtrust.org.uk/scotland/rhi](http://www.energysavingtrust.org.uk/scotland/rhi).

| Heat demand                  | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 5,444             | (266)                     | N/A                              | (2,197)                         |
| Water heating (kWh per year) | 1,546             |                           |                                  |                                 |

## Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

## About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst ([www.elmhurstenergy.co.uk](http://www.elmhurstenergy.co.uk)), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk) and entering the report reference number (RRN) printed at the top of this page.

|                             |  |
|-----------------------------|--|
| Assessor's name:            | Mr. Andrew MacKenzie   |
| Assessor membership number: | EES/018471   |
| Company name/trading name:  | Home Report Company  |
| Address:                    | 14 Rutland Square<br>Midlothian/Edinburghshire<br>Edinburgh<br>EH1 2BD             |
| Phone number:               | 0  |
| Email address:              | <a href="mailto:andrew@homereportcompany.co.uk">andrew@homereportcompany.co.uk</a> |
| Related party disclosure:   | No related party   |

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

## Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk), with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at [www.gov.scot/epc](http://www.gov.scot/epc).


## **Opportunity to benefit from a Green Deal on this property**

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit [www.greenerscotland.org](http://www.greenerscotland.org) or call 0808 808 2282.







## SINGLE SURVEY



PROVIDING HOME REPORTS AT A TIME THAT SUITS YOU

[WWW.HOMEREPORTCOMPANY.CO.UK](http://WWW.HOMEREPORTCOMPANY.CO.UK)

# Single Survey

|                           |  |
|---------------------------|--|
| <b>Property address</b>   | FLAT 3/2<br>91 BARLOGAN AVENUE<br>GLASGOW<br>G52 1AG |
| <b>Customer</b>           | J CRAIG  |
| <b>Customer address</b>   | FLAT 3/2<br>91 BARLOGAN AVENUE<br>GLASGOW<br>G52 1AG |
| <b>Prepared by</b>        | Home Report Company                                  |
| <b>Date of Inspection</b> | 24 <sup>th</sup> MAY 2018                            |



# Single Survey

## 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

|  |   |
|--|---|
| <b>Description</b>                               | The subjects comprise the north-west most top floor flat contained within a four storey end terrace tenement containing 11 residential flats.   |
| <b>Accommodation</b>                             | Third (top) floor – hallway, living room with kitchenette off, bedroom and three-piece bathroom suite.  |
| <b>Gross internal floor area (m<sub>2</sub>)</b> | 40m <sup>2</sup> or thereby   |
| <b>Neighbourhood and location</b>                | The subjects are located within the mixed residential/commercial district of Craigton to the south-west of Glasgow city centre where surrounding properties are of comparable age, type and character. All normal local amenities and facilities are available within the locality. |
| <b>Age</b>                                       | Fully 100 years old.  |
| <b>Weather</b>                                   | Dry following a period of predominately mixed weather.  |
| <b>Chimney Stacks</b>                            | <b>Visually inspected with the aid of binoculars where appropriate.</b><br>From our restricted external ground floor inspection the communal chimney stacks appear to be of stone construction. Restricted visual inspection carried out.   |

# Single Survey

|                                     |  |
|-------------------------------------|--|
| <b>Roofing including roof space</b> | <p><b>Sloping roofs where visually inspected.</b></p> <p><b>Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.</b></p> <p><b>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.</b></p> <p>Main roof structure as from our restricted external ground floor inspection appears to be pitched clad externally with tiles.</p> <p>We confirm that no access was gained onto the external roof structure and inadequate vantage available from ground floor level, therefore the external roof structure was not fully inspected.</p> <p>Our inspection of the communal roof void area accessed via a hatch at the top floor landing within the common stairwell was restricted to a visual inspection from the access hatch and areas directly adjacent.</p> <p>We confirm that no access was gained into the roof void due to unsafe footing.</p> |
| <b>Rainwater fittings</b>           | <p><b>Visually inspected with the aid of binoculars where appropriate.</b></p> <p>Rainwater fittings were noted to be cast iron and PVC construction.</p>  |
| <b>Main walls</b>                   | <p><b>Visually inspected with the aid of binoculars where appropriate.</b></p> <p><b>Foundations and concealed parts were not exposed or inspected.</b></p> <p>Main walls were noted to be of stone construction with a part roughcast rear elevation.</p>   |

# Single Survey

|  |  |
|--|--|
| <b>Windows, external doors and joinery</b> | <p><b>Internal and external doors were opened and closed where keys were available.</b></p> <p><b>Random windows were opened and closed where possible.</b></p> <p><b>Doors and windows were not forced open.</b></p> <p>Windows were noted to be of timber single glazed design, whilst the access door to the flat was noted to be of UPVC double glazed design.</p> |
| <b>External decorations</b>                | <p><b>Visually inspected.</b></p> <p>Painted.</p>  |
| <b>Conservatories / porches</b>            | <p><b>Visually inspected.</b></p> <p>None.</p>   |
| <b>Communal areas</b>                      | <p><b>Circulation areas visually inspected.</b></p> <p>Communal access stairwell along with a communal courtyard to the rear of the block in which the subjects are contained.</p>   |
| <b>Garages and permanent outbuildings</b>  | <p><b>Visually inspected.</b></p> <p>None.</p>   |
| <b>Outside areas and boundaries</b>        | <p><b>Visually inspected.</b></p> <p>The subjects would appear to have access to a communal courtyard area to the rear of the block in which the subjects are contained.</p>   |

# Single Survey

|  |   |
|--|---|
| <b>Ceilings</b>                              | <p><b>Visually inspected from floor level.</b></p> <p>Ceilings were noted to be of plasterboard construction with painted finishes. Timber panels also noted.</p>   |
| <b>Internal walls</b>                        | <p><b>Visually inspected from floor level.</b></p> <p><b>Using a moisture meter, walls were randomly tested for dampness where considered appropriate.</b></p> <p>Internal walls were noted to be of solid and stud plasterboard construction with papered and/or painted finishes.</p>   |
| <b>Floors including sub floors</b>           | <p><b>Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted,</b></p> <p><b>Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted “head and shoulders” inspection at the access point.</b></p> <p><b>Physical access to the sub floor area may be taken if the Surveyor deems it safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.</b></p> <p>Flooring appears to be of suspended timber construction with fitted floor covering throughout. No access gained to any sub floor areas at the time of inspection, and overall inspection of flooring restricted due to fitted floor coverings.</p> |
| <b>Internal joinery and kitchen fittings</b> | <p><b>Built-in cupboards were looked into but no stored items were moved.</b></p> <p><b>Kitchen units were visually inspected excluding appliances.</b></p> <p>Internal doors are of timber design. Facings and skirtings are of painted moulded design, and the kitchen is equipped with a range of wall and base units.</p>   |
| <b>Chimney breasts and fireplaces</b>        | <p><b>Visually inspected.</b></p> <p><b>No testing of the flues or fittings was carried out.</b></p> <p>None.</p>   |

# Single Survey

|   |   |
|---|---|
| <b>Internal decorations</b>               | <b>Visually inspected.</b><br>Walls papered and/or painted, woodwork generally painted. Bathroom walls are partly tiled.  |
| <b>Cellars</b>                            | <b>Visually inspected.</b><br>None.   |
| <b>Electricity</b>                        | <b>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them off.</b><br><br>Mains serving 13-amp supply with fuse box located within a hallway cupboard. |
| <b>Gas</b>                                | <b>Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them off.</b><br><br>Mains supply. Meter located within hallway cupboard.                         |
| <b>Water, plumbing, bathroom fittings</b> | <b>Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.</b><br><b>No tests whatsoever were carried out to the system or appliances.</b><br><br>Mains supply. Internal distribution pipes where seen appear to be of copper and PVC design.<br><br>Sanitary arrangements comprise a three-piece bathroom suite.  |

# Single Survey

|                                       |   |
|---------------------------------------|---|
| <b>Heating and hot water</b>          | <p><b>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.</b></p> <p><b>No tests whatsoever were carried out to the system or appliances.</b></p> <p>Gas fired Sime boiler to radiators.</p> <p>Hot water is assumed to be supplied on demand from the aforementioned gas fired boiler.</p> |
| <b>Drainage</b>                       | <p><b>Drainage covers etc. were not lifted.</b></p> <p><b>Neither drains nor drainage systems were tested.</b></p> <p>Mains.</p>  |
| <b>Fire, smoke and burglar alarms</b> | <p><b>Visually inspected.</b></p> <p><b>No tests whatsoever were carried out to the system or appliances.</b></p> <p>None.</p>  |



# Single Survey

## Any additional limits to inspection

**For flats / maisonettes. Only the subject flat and internal communal areas giving access to the flat were inspected. If the roof space or under-building / basement is communal, reasonable and safe access is not always possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation. The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.**

The property was inspected within the limits imposed. At the time of inspection, the property was furnished with floor coverings fitted throughout, which restricted our overall inspection. Items were not removed from cupboards. Services were not tested.

No access was gained to any sub-floor areas. Where walls are lined internally, for example with plasterboard, tiling or timber, the structure behind the lining could not be tested with an electronic moisture meter.

Our inspection of the external fabric in general restricted as inspected from external ground floor level.

We confirm that no access was gained onto the external roof structure and inadequate vantage available from ground floor level, therefore the external roof structure was not fully inspected.

Our inspection of the communal roof void area accessed via a hatch at the top floor landing within the common stairwell was restricted to a visual inspection from the access hatch and areas directly adjacent.

We confirm that no access was gained into the roof void due to unsafe footing.

Although considerable care was taken during the course of our inspection to detect defects serious in nature, we were unable to inspect those parts of the property which were covered, concealed or inaccessible and cannot, therefore guarantee that any such parts of the property are entirely free from defect.

It will be appreciated that parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.

This report does not constitute a full and detailed description of the property and a structural investigation was not carried out. No inspection was undertaken of woodwork or other parts of the structure which are covered, unexposed or otherwise inaccessible and as a result no guarantee can be given that such parts of the structure are free from rot, beetle or other defects.

No removal of internal linings has been carried out in order to ascertain the condition of hidden parts and no warranty can be given regarding the areas not specifically referred to in this report.

# Single Survey

The external building fabric has been inspected from ground level only from the subject's grounds and where possible from adjoining public property. Exposure work has not been carried out.


I have not carried out an inspection for Japanese Knotweed and unless otherwise stated for the purposes of this report I have assumed that there is no Japanese Knotweed within the boundaries of the property or in neighbouring properties.

It is out with the scope of this inspection to determine whether or not asbestos based products are present within the property. Asbestos was widely used in the building industry until around 1999, when it became a banned substance. If you have any concerns, you should engage the services of a qualified asbestos surveyor.

The construction materials described in this report should not be considered as an exact specification. They are described for general guide only and based on a non-disruptive, visual inspection as defined in the main Terms & Conditions. Some descriptions may be partial and/or assumed. No detailed analysis, sampling or testing of materials has been undertaken.

# Single Survey

## Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

# Single Survey

| Category 3   | Category 2  | Category 1                               |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

## Structural Movement

| Repair Category | Category 2  |
|-----------------|---|
| <b>Notes</b>    | <p>All buildings move daily and seasonally as a result of external factors such as gravity, temperature, moisture content and vibrations. Consequently, most buildings will have minor non-structural cracks related to these factors. Minor cracks can be filled during normal redecoration but often recur seasonally due to normal movement in a building. Non-structural cracks of this nature will not be recorded or reported.</p> <p>There is evidence of pronounced structural movement in the form of off level building lines and internal flooring deflection. It is understood the property has been subject to structural repairs and there are steel pins and steel supports noted on the rear elevation. Our valuation assumes that work was properly supervised and complied with all necessary permissions and all documentation should be obtained and transferred at the time of the sale.</p> |

## Dampness, rot and infestation

| Repair Category | Category 1  |
|-----------------|---|
| <b>Notes</b>    | <p>Random testing, where accessible, was carried out with an electronic moisture meter throughout the property.</p> <p>There was no evidence found of significant dampness, rot or infestation within those areas of the property available for inspection.</p> |

## Chimney Stacks

| Repair Category | Category 2   |
|-----------------|--|
| <b>Notes</b>    | Render/masonry finishes were beginning to show signs of deterioration. |

## Roofing including roof space

| Repair Category | Category 2   |
|-----------------|--|
| <b>Notes</b>    | <p><u>Roof</u></p> <p>The roof was noted to be in fair order commensurate with the age and type of property although some ongoing maintenance and repairs are likely to be required.</p> |

# Single Survey

|  |   |
|--|---|
|  | <p><u>Void</u></p> <p>Restricted visual inspection from the access hatch, and the areas directly adjacent to the hatch only. The majority of the common roof void were not visible or inspected at the time of our inspection and should not be considered free from defects. Damp staining noted to internal roof timbers.</p> |
| <b>Rainwater Fittings</b>                  |   |
| <b>Repair Category</b>                     | <b>Category 2</b>   |
| <b>Notes</b>                               | There is evidence of corrosion which may result in leakage.   |
| <b>Main Walls</b>                          |   |
| <b>Repair Category</b>                     | <b>Category 2</b>   |
| <b>Notes</b>                               | <p>The external render is defective in places with cracked and boss sections being evident.</p> <p>There is weathering and erosion of stonework.</p>  |
| <b>Windows, external doors and joinery</b> |   |
| <b>Repair Category</b>                     | <b>Category 2</b>   |
| <b>Notes</b>                               | <p>Windows would appear to be of an older replacement type. Draughts could be felt adjacent to some of the window units.</p> <p>Overhaul/repair works are required to external decorative finishes including possible repairs to external joinery work prior to redecoration.</p>   |
| <b>External decorations</b>                |   |
| <b>Repair Category</b>                     | <b>Category 2</b>   |
| <b>Notes</b>                               | Overhaul/repair works are required to external decorative finishes including possible repairs to external joinery work prior to redecoration.   |
| <b>Conservatories/porches</b>              |   |
| <b>Repair Category</b>                     | -   |
| <b>Notes</b>                               | Not applicable.   |

# Single Survey

| Communal areas                     |  |
|------------------------------------|--|
| <b>Repair Category</b>             | <b>Category 2</b>  |
| <b>Notes</b>                       | Communal areas serving the property require repair and redecoration.<br>Damp staining was noted to the internal wall and ceilings within the common stairwell which requires to be monitored with any necessary repairs being implemented.         |
| Garages and permanent outbuildings |  |
| <b>Repair Category</b>             | -  |
| <b>Notes</b>                       | Not applicable.  |
| Outside areas and boundaries       |  |
| <b>Repair Category</b>             | <b>Category 1</b>  |
| <b>Notes</b>                       | The boundaries appear reasonably well defined and fences etc., are in adequate condition. Regular maintenance will be required.<br>You should verify with your conveyancer the extent of the boundaries attaching to the property.                 |
| Ceilings                           |  |
| <b>Repair Category</b>             | <b>Category 1</b>  |
| <b>Notes</b>                       | Within the limits of our inspection these generally appeared in fair condition consistent with age. During redecoration some plaster filling/repair may be required.<br>Timber panelling noted we assume a suitable fire coating has been applied. |
| Internal Walls                     |  |
| <b>Repair Category</b>             | <b>Category 1</b>  |
| <b>Notes</b>                       | The internal walls are largely covered with decorative finishes. During routine redecoration some plaster filling may be necessary.  |

# Single Survey

| Floors including sub-floors           |  |
|---------------------------------------|--|
| <b>Repair Category</b>                | <b>Category 1</b>  |
| <b>Notes</b>                          | <p>No access to the sub-floor chamber was possible at the time of our visit to the property. Within the limitations of our surface inspection there was no indication to suggest significant defects in this area. It will, however be appreciated that the area was not inspected and therefore no guarantees can be provided in this regard.</p> <p>Areas of loose/uneven flooring were noted.</p> |
| Internal joinery and kitchen fittings |  |
| <b>Repair Category</b>                | <b>Category 1</b>  |
| <b>Notes</b>                          | <p>The internal joinery is generally in keeping with the age and type of property and appeared in fair condition consistent with age.</p> <p>The kitchen units are of a modern type and appeared in adequate condition for their age and purpose.</p>  |
| Chimney breasts and fireplaces        |  |
| <b>Repair Category</b>                | <b>Category 1</b>  |
| <b>Notes</b>                          | <p>All original fireplaces have been removed/blocked and assume adequately vented.</p> <p>All flue linings should be checked, repaired as necessary and swept prior to the fires being reused.</p> <p>Advise vent blanked off fireplaces as this can lead to problems of condensation and/or dampness developing.</p>  |
| Internal decorations                  |  |
| <b>Repair Category</b>                | <b>Category 1</b>  |
| <b>Notes</b>                          | <p>Internal decorations are in acceptable condition. Internal decorations are a matter of personal taste and you may wish to redecorate regardless.</p>  |
| Cellars                               |  |
| <b>Repair Category</b>                | -  |
| <b>Notes</b>                          | Not applicable   |

# Single Survey

| Electricity                           |  |
|---------------------------------------|--|
| <b>Repair Category</b>                | <b>Category 2</b>  |
| <b>Notes</b>                          | <p>It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.</p> <p>The electrical system is on semi modern lines and as such we recommend that it be checked and upgraded as necessary by an NICEIC registered Electrical Contractor</p>   |
| Gas                                   |  |
| <b>Repair Category</b>                | <b>Category1</b>   |
| <b>Notes</b>                          | <p>It is outwith our remit to carry out tests and as a precautionary measure it is appropriate to have the gas fittings tested by a Gas Safe Registered Engineer.</p>  |
| Water, plumbing and bathroom fittings |  |
| <b>Repair Category</b>                | <b>Category 1</b>  |
| <b>Notes</b>                          | <p>The property appears connected to mains supplies of water.</p> <p>The plumbing and fittings appear of copper/pvc piping where seen and appeared in serviceable condition but was not tested.</p> <p>The sanitary fittings are of modern style and type.</p> <p>Flooring beneath the bath was not inspected, however it should be appreciated that over time the build-up of condensation together with small amounts of leakage from joints between tiling or mastic and bath/shower fittings can lead to deterioration of flooring or wall linings and repairs in this regard should be anticipated and budgeted for as part of a normal and ongoing maintenance regime.</p> |
| Heating and hot water                 |  |
| <b>Repair Category</b>                | <b>Category 2</b>  |
| <b>Notes</b>                          | <p>There is a gas fired central heating system and gas fittings and these should all be checked and serviced in the normal manner. In the interests of safety it would be prudent to have all gas appliances checked by a Gas Safe registered tradesman.</p> <p>It is not uncommon for incoming purchasers to test / service the central heating boiler when taking occupancy. Regular servicing of the boilers will help maintain them in a workable and efficient condition.</p>   |



# Single Survey

| Drainage               |  |
|------------------------|--|
| <b>Repair Category</b> | <b>Category 1</b>  |
| <b>Notes</b>           | The property is thought to be connected to a main sewer. There was no surface evidence to suggest the system is choked or leaking. |

# Single Survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

|  |          |
|--|----------|
| <b>Structural Movement</b>                   | <b>2</b> |
| <b>Dampness, rot and infestation</b>         | <b>1</b> |
| <b>Chimney stacks</b>                        | <b>2</b> |
| <b>Roofing including roof space</b>          | <b>2</b> |
| <b>Rainwater fittings</b>                    | <b>2</b> |
| <b>Main walls</b>                            | <b>2</b> |
| <b>Windows, external doors and joinery</b>   | <b>2</b> |
| <b>External decorations</b>                  | <b>2</b> |
| <b>Conservatories / porches</b>              | <b>-</b> |
| <b>Communal areas</b>                        | <b>2</b> |
| <b>Garages and permanent outbuildings</b>    | <b>-</b> |
| <b>Outside areas and boundaries</b>          | <b>1</b> |
| <b>Ceilings</b>                              | <b>1</b> |
| <b>Internal walls</b>                        | <b>1</b> |
| <b>Floors including sub-floors</b>           | <b>1</b> |
| <b>Internal joinery and kitchen fittings</b> | <b>1</b> |
| <b>Chimney breasts and fireplaces</b>        | <b>1</b> |
| <b>Internal decorations</b>                  | <b>1</b> |
| <b>Cellars</b>                               | <b>-</b> |
| <b>Electricity</b>                           | <b>2</b> |
| <b>Gas</b>                                   | <b>1</b> |
| <b>Water, plumbing and bathroom fittings</b> | <b>1</b> |
| <b>Heating and hot water</b>                 | <b>2</b> |
| <b>Drainage</b>                              | <b>1</b> |

## Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

## Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

## Category 1

No immediate action or repair is needed.

### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

# Single Survey

## 3. Accessibility information

### Guidance notes for accessibility information

*Three steps or fewer to a main entrance door of the property:* In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift. *Unrestricted parking within 25 metres:* For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

|  |             |
|--|-------------|
| 1. Which floor(s) is the living accommodation on?                                      | Third floor |
| 2. Are there three steps or fewer to a main entrance door of the property?             | No          |
| 3. Is there a lift to the main entrance door of the property?                          | No          |
| 4. Are all door openings greater than 750mm?   | No          |
| 5. Is there a toilet on the same level as the living room and kitchen?                 | Yes         |
| 6. Is there a toilet on the same level as a bedroom?                                   | Yes         |
| 7. Are all rooms on the same level with no internal steps or stairs?                   | Yes         |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes         |

## Matters for a solicitor or licensed conveyancer

Absolute Ownership assumed.

We are unaware of any easements, servitudes or rights of way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds.

We assume that the carriageways etc., ex adverso the subjects are the responsibility of the local authority.

If the legal advisers find that there are significant variations from the standard assumptions, then this should be referred back to the surveyor. In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

The subjects form part of a block of flats and it has been assumed that maintenance/repair costs of the common parts of the building and external grounds will be shared on an equitable basis with the adjoining proprietors. It is therefore assumed that the costs of repairs detailed within this report which relate to these areas should be apportioned accordingly, although exact liability should be confirmed.

It should be confirmed if a Factor has been appointed to the building. A Factor can advise on any annual maintenance charges and if there is a block insurance policy in place.

The property benefits from assumed common external grounds. There are a number of boundary fence structures. It is always sensible when purchasing any property to find out who owns all outside areas/boundaries and who is responsible for their maintenance. Your legal advisors will obtain this information.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialists or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

The valuation is made on the assumption that any alterations that may have been carried out to the property satisfy all relevant legislation and have full certification where appropriate.

Replacement windows have been installed and we advise that the vendors be approached to confirm compliance or otherwise with current Building and if applicable Planning Regulations.

## Estimated reinstatement cost for insurance purposes

We are of the opinion that the subjects should be insured for buildings reinstatement purposes for a sum of not less than £110,000 (ONE HUNDRED AND TEN THOUSAND POUNDS STERLING).

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction, on a reinstatement basis, assuming reconstruction of the property in its existing design and materials. Finishing's and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised. The figure should be reviewed annually and in light of any future alterations or additions.


## Valuation and market comments

We are of the opinion that the market value of the subjects all as previously described and on a vacant possession basis as at the 24<sup>th</sup> May 2018 would be fairly stated in the region of £50,000 (FIFTY THOUSAND POUNDS STERLING).

We have endeavoured to reflect the general condition of the property, location and current market conditions when arriving at our opinion of valuation. We would assume that current trends will prevail at the ultimate date of disposal with no adverse or onerous matters being introduced into the market during the intervening period which would have a detrimental effect on price.

The result of the UK referendum to leave the EU has created uncertainty within the market, and it should be appreciated that the valuation is based on the most recent comparable evidence available.

This report is not the product of a building survey and all defects and other matters should be fully considered and, where appropriate, be the subject of specialist and tradesmen's reports prior to the conclusion of Missives.

|                       |  |
|-----------------------|--|
| <b>Signed</b>         |  |
| <b>Report author</b>  | Mr Andrew J MacKenzie Bsc(Hons) MRICS<br>For and on behalf of Home Report Company    |
| <b>Address</b>        | 272 Bath Street, GLASGOW, G2 4JR   |
| <b>Date of report</b> | 24 <sup>th</sup> May 2018  |

# Terms and Conditions

## PART 1 – GENERAL

### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and Energy Performance Certificate in the format prescribed by the accredited Energy Company.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. (1)

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any part other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

(1) Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

# Terms and Conditions

## 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- The Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular; the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

## 1.4 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

## 1.5 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

## 1.6 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the Surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

# Terms and Conditions

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

## 1.7 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

## 1.8 DEFINITIONS

- The “Lender” is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the “Market Value” is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the “Property” is the property which forms the subject of the Report;
- the “Purchaser” is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a “prospective Purchaser” is anyone considering buying the Property;
- the “Report” is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the “Seller” is/are the proprietor(s) of the Property;
- the “Surveyor” is the author of the Report on the Property; and
- the “Surveyors” are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the “Surveyors” means the Surveyor) whose details are set out at the head of the Report;
- the “Energy Report” is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.



## PART 2 – DESCRIPTION OF THE REPORT

### 1.9 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company.

### 1.10 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible – in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the Report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey or properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### 2.1 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

1. Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.

# Terms and Conditions

3. Category 1: No immediate action or repair is needed.

## **WARNING:**

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an exposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

## **2.2 SERVICES**

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is a cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances

## **2.3 ACCESSIBILITY**

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

## **2.4 ENERGY REPORT**

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

## **2.5 VALUATION AND CONVEYANCER ISSUES**

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc from the valuation. In the case of flats, the following further assumptions are made that:

There are rights of access and exit over all communal roadways, corridors, stairways etc and to use communal grounds, parking areas, and other facilities.

There are no particularly troublesome or unusual legal restrictions.

There is no current dispute between the occupiers of the flats or any outstanding claims or losses and the costs of repairs to the building are shared amongst the co-proprietors on an equitable basis.

# Terms and Conditions

Any additional assumption, or any found not to apply, is reported.

“Re-instatement cost” is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.



# PROPERTY QUESTIONNAIRE



PROVIDING HOME REPORTS AT A TIME THAT SUITS YOU

[WWW.HOMEREPORTCOMPANY.CO.UK](http://WWW.HOMEREPORTCOMPANY.CO.UK)

# property questionnaire

|   |  |
|---|--|
| Property address                          | <b>3, 2, 91 Barlogan Avenue<br/>Craigton<br/>Glasgow<br/>G52 1AG</b> |
| Seller(s)                                 | <b>Mr &amp; Mrs David</b>  |
| Completion date of property questionnaire | <b>24/05/2018</b>  |

## Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

## Information to be given to prospective buyer(s)

|    |  |                        |
|----|--|------------------------|
| 1. | Length of ownership  |                        |
|    | How long have you owned the property?  | <b>11years 2months</b> |
| 2. | Council tax  |                        |
|    | Which Council Tax band is your property in?  | <b>Band A</b>          |
| 3. | Parking  |                        |
|    | <p>What are the arrangements for parking at your property?</p> <p><b>On Street</b></p> <p>Any other parking information: <i>N/A</i></p>  |                        |
| 4. | Conservation area  |                        |
|    | Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)? | <b>No</b>              |

# property questionnaire

|    |   |            |
|----|---|------------|
| 5. | Listed buildings  |            |
|    | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?  | <b>No</b>  |
| 6. | Alterations/additions/extensions  |            |
| a. | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?   | <b>No</b>  |
|    | Please describe below the changes which you have made:  |            |
|    | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?   | N/A        |
|    | <p>The relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.</p> <p>If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:</p> <p>N/A</p> |            |
| b. | Have you had replacement windows, doors, patio doors or double glazing installed in your property?  | <b>Yes</b> |
|    | (i) Were the replacements the same shape and type as the ones you replaced?   | <b>Yes</b> |
|    | (ii) Did this work involve any changes to the window or door openings?  | <b>No</b>  |
|    | <p>(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):</p> <p><b>New Front Door</b></p> <p>Please give any guarantees which you received for this work to your solicitor or estate agent.</p>                                       |            |

# property questionnaire

|    |   |                     |
|----|---|---------------------|
| 7. | Central heating   |                     |
| a. | Is there a central heating system in your property?<br><i>(Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).</i> | <b>Yes</b>          |
|    | What kind of central heating is there?  | <b>Gas Warm Air</b> |
|    | i) When was your central heating system or partial central heating system installed?  | <b>Dont know</b>    |
|    | (ii) Do you have a maintenance contract for the central heating system?   | <b>Yes</b>          |
|    | Please give details of the company with which you have a maintenance contract:<br><b>Scottish Gas</b>   |                     |
|    | (iii) When was your maintenance agreement last renewed?   | <b>April 2018</b>   |
| 8. | Energy Performance Certificate  |                     |
|    | Does your property have an Energy Performance Certificate which is less than 10 years old?  | <b>No</b>           |
| 9. | Issues that may have affected your property   |                     |
| a. | Has there been any storm, flood, fire or other structural damage to your property while you have owned it?  | <b>No</b>           |
|    | Is the damage the subject of any outstanding insurance claim?   | N/A                 |
| b. | Are you aware of the existence of asbestos in your property?  | <b>No</b>           |
|    | Please give details:<br>N/A   |                     |



| 10.                                 | Services   |                        |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
|-------------------------------------|--|------------------------|---------|-----------|----------|-----------------------------|------------------|---------------------|-------------------------------------|------------------|------------------------|-------------|------------------|---------------------|----------------|----------------------|-----|-----------|------------------|------------|-----------------------|------------------|------------|-----------|------------------|------------|
| a.                                  | Please list which services are connected to your property and give details of the supplier:  |                        |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
|                                     | <table border="1"> <thead> <tr> <th>Service</th> <th>Connected</th> <th>Supplier</th> </tr> </thead> <tbody> <tr> <td>Gas or liquid petroleum gas</td> <td><b>Connected</b></td> <td><b>Scottish Gas</b></td> </tr> <tr> <td>Water mains or private water supply</td> <td><b>Connected</b></td> <td><b>Glasgow Council</b></td> </tr> <tr> <td>Electricity</td> <td><b>Connected</b></td> <td><b>Scottish Gas</b></td> </tr> <tr> <td>Mains drainage</td> <td><b>Not Connected</b></td> <td>N/A</td> </tr> <tr> <td>Telephone</td> <td><b>Connected</b></td> <td><b>Sky</b></td> </tr> <tr> <td>Cable TV or satellite</td> <td><b>Connected</b></td> <td><b>Sky</b></td> </tr> <tr> <td>Broadband</td> <td><b>Connected</b></td> <td><b>Sky</b></td> </tr> </tbody> </table> |                        | Service | Connected | Supplier | Gas or liquid petroleum gas | <b>Connected</b> | <b>Scottish Gas</b> | Water mains or private water supply | <b>Connected</b> | <b>Glasgow Council</b> | Electricity | <b>Connected</b> | <b>Scottish Gas</b> | Mains drainage | <b>Not Connected</b> | N/A | Telephone | <b>Connected</b> | <b>Sky</b> | Cable TV or satellite | <b>Connected</b> | <b>Sky</b> | Broadband | <b>Connected</b> | <b>Sky</b> |
| Service                             | Connected  | Supplier               |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| Gas or liquid petroleum gas         | <b>Connected</b>   | <b>Scottish Gas</b>    |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| Water mains or private water supply | <b>Connected</b>   | <b>Glasgow Council</b> |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| Electricity                         | <b>Connected</b>   | <b>Scottish Gas</b>    |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| Mains drainage                      | <b>Not Connected</b>   | N/A                    |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| Telephone                           | <b>Connected</b>   | <b>Sky</b>             |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| Cable TV or satellite               | <b>Connected</b>   | <b>Sky</b>             |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| Broadband                           | <b>Connected</b>   | <b>Sky</b>             |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
| b.                                  | Is there a septic tank system at your property?  | <b>Yes</b>             |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
|                                     | i) Do you have appropriate consents for the discharge from your septic tank?   | <b>Don't Know</b>      |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
|                                     | (ii) Do you have a maintenance contract for your septic tank?  | <b>No</b>              |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
|                                     | Please give details of the company with which you have a maintenance contract:<br>N/A  |                        |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |
|                                     | (iii) When was your maintenance agreement last renewed?  | N/A                    |         |           |          |                             |                  |                     |                                     |                  |                        |             |                  |                     |                |                      |     |           |                  |            |                       |                  |            |           |                  |            |

# property questionnaire

|     |   |                       |
|-----|---|-----------------------|
| 11. | Responsibilities for shared or common areas   |                       |
| a.  | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?   | <b>No</b>             |
|     | Please give details:<br>N/A   |                       |
| b.  | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?  | <b>Not applicable</b> |
|     | Please give details:<br>N/A   |                       |
| c.  | Has there been any major repair or replacement of any part of the roof during the time you have owned the property?   | <b>No</b>             |
|     | Please give details:<br>N/A   |                       |
| d.  | Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?   | <b>No</b>             |
|     | Please give details:<br>N/A   |                       |
| e.  | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?   | <b>No</b>             |
|     | Please give details:<br>N/A   |                       |
| f.  | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) | <b>No</b>             |
|     | Please give details:<br>N/A   |                       |
| 12. | Charges associated with your property   |                       |
| a.  | Is there a factor or property manager for your property?  | <b>Yes</b>            |
|     | Please provide the name and address, and give details of any deposit held and any charges:<br><b>Redpath Bruce\r\nCrown House\r\n152 West Regent Street\r\nGlasgow\r\nG52 1AG</b>                               |                       |

# property questionnaire

|     |   |            |
|-----|---|------------|
| b.  | Is there a common buildings insurance policy?   | <b>Yes</b> |
|     | Is the cost of the insurance included in your monthly/annual factor's charges?  | <b>Yes</b> |
| c.  | Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.<br><br>N/A   |            |
| 13. | Specialist works  |            |
| a.  | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?   | <b>Yes</b> |
|     | Please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property:<br><br><b>Dry Rot 2017</b>  |            |
| b.  | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?  | <b>No</b>  |
|     | Please give details:<br><br>N/A   |            |
| c.  | Do you have any guarantees relating to this work?   | <b>No</b>  |
|     | <p>These guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.</p> <p>Guarantees are held by:<br/><br/>N/A</p> |            |

|       |  |                   |
|-------|--|-------------------|
| 14.   | Guarantees   |                   |
| a.    | Are there any guarantees or warranties for any of the following:   |                   |
| (i)   | Electrical work  | <b>Don't know</b> |
| (ii)  | Roofing  | <b>Don't know</b> |
| (iii) | Central heating  | <b>Don't know</b> |
| (iv)  | National House Building Council (NHBC)   | <b>Don't know</b> |
| (v)   | Damp course  | <b>Don't know</b> |
| (vi)  | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)   | <b>No</b>         |
| b.    | If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):<br><br>N/A |                   |
| c.    | Are there any outstanding claims under any of the guarantees listed above?   | <b>No</b>         |
|       | Please give details:<br><br>N/A  |                   |
| 14.   | Boundaries   |                   |
|       | So far as you are aware, has any boundary of your property been moved in the last 10 years?  | <b>Don't know</b> |
|       | Please give details:<br><br>N/A  |                   |

# property questionnaire

|     |   |           |
|-----|---|-----------|
| 16. | Notices that affect your property   |           |
|     | In the past three years have you ever received a notice:  |           |
| a.  | advising that the owner of a neighbouring property has made a planning application?   | <b>No</b> |
| b.  | that affects your property in some other way?   | <b>No</b> |
| c.  | that requires you to do any maintenance, repairs or improvements to your property?  | <b>No</b> |
|     | If you have answered yes to any of a–c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property. |           |

Declaration by the seller(s)/or other authorised body or person(s).

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):

**Janet Craig**

---

Date:

**24/05/2018**

---



# HOME REPORT



## EDINBURGH HEAD OFFICE

14 RUTLAND SQUARE  
EDINBURGH  
EH1 2BD

## GLASGOW

272 BATH STREET  
GLASGOW  
G2 4JR

## ABERDEEN

111 GALLOWGATE  
ABERDEEN  
AB25 1BU

[INFO@HOMEREPORTCOMPANY.CO.UK](mailto:INFO@HOMEREPORTCOMPANY.CO.UK)

PROVIDING HOME REPORTS AT A TIME THAT SUITS YOU

[WWW.HOMEREPORTCOMPANY.CO.UK](http://WWW.HOMEREPORTCOMPANY.CO.UK)