Serial No:

12606105

PART 1

LEGIONELLA RISK ASSESSMENT

	700E00MENT			
Auditor Details	Audited Property Address	Landlord/Agent Address	500	300
Trinity Park Heating Solutions	Name:	111		
29 Talisker Avenue.	Address: 4 ONKNEY Drive	Address:) 2-24 JOHN FINNE		0.000
Kilmarnock	KUMPNICH, KAZ ZHB	STREET, NICMANYOUG	POVV	VIE
Tel. No: 07340 763827	10/20 17/1/	KA3 IDD		
	Tel. No:	Tel. No:		
Date Of Audit: 30/9/19	Date Of Review: 10/4/70	Property Type: Flous &		
THE RISK ASSESSMENT			Ye:	s N
Did you consider whether you could eliminate the ri	sk?		/	7
Is there any tenant, resident or regular visitor susce	eptible to Legionella due to age, health or lifestyle?		\top	1
Did the person carrying out the assessment have access to competent help and advice when carrying out the assessment?				1
Describe type of cold water system e.g. mains feed		MAINS FED		
Describe type of hot water system e.g. mains feed v	via a combi boiler or from conventional boiler and s	torage tank: VIA COM	7	
RISK CATEGORY - Water Outlet Temperature		227 000	The state of the s	s No
Is the cold water temperature at outlets below 20°C within 2 minutes?				
Is the hot water temperature above 50°C at outlets v	Is the hot water temperature above 50°C at outlets within 1 minute?			
Cold water must flow from outlets at below 20°C and made to the system such as lagging of piperwork or	d hot water above 50°C to minimise risk. If tempera adjustment of temperature settings for hot water.	ntures ar too low/high then adjustments ne	ed to be	e
Identified Defect/Risk	Recommendations			1000
				DE ONE PE
RISK CATEGORY - Cold Water Systems			Yes	No
Is a cold water storage tank present?			165	V
Is the cold water tank accessible?			+-	+-
Cold water storage tank location:				
Does the cold water storage tank have a tight fitting li	id?		_	Т
Is the water in the tank clean and free from rust, debr	ris, scale and organic matter?		+-	+
Is the temperature of the water in the tank below 20°C?				\vdash
Is the cold water tank insulated?				+-
If any debris etc is present in the system it should be drained All cold water tanks should have tight fitting lids to prevent de	PORS FROM ENTERING THE SYSTEM			
The water in the tank should be below 20°C and the tankshood	uid be insulated to prevent the temperature rising above the	nis level		
dentined Delectrisk	Recommendations			
DISK CATTOONY II AWAY				
RISK CATEGORY - Hot Water Systems			Yes	No
Is the temperature setting on the boiler and/or hot water tank such that hot water is heated to and stored at a temperature of 60°C?				
Are the hot water distribution pipes insulated?				
f more than one calorifier is used are they connected in parallel?				
Does the calorifier have the following fitted:				
drain valve?				
temperature gauge on the inlet and outlet?				
n access panel?				
the temperature is set at above 60°C this can cause scalding	g to users. The temperature setting on the boiler and/or ho	ot water tank should be set and maintained at 60)°C	
lentified Defect/Risk	Recommendations	Reference of the second	1000	18/9
				- 1

PART 2

LEGIONELLA RISK ASSESSMENT

DIOK CATEGORY 1:41-11-10-414		. No
RISK CATEGORY - Little Used Outlets		
Are there any water outlets that are used less than once per week? e.g. guest bathrooms		
If Yes, are there arrangements in place to flush them through on atleast a weekly basis?		
Any little used outlets should be flushed through weekly by running water through the outlet for atleas	t 2 minutes. Aerosol production should be minimised during this process.	
Identified Defect/Risk Recomm	nendations	
RISK CATEGORY - Shower Heads	Yes	No
Are there any showers in the property?	V	1
If Yes, identify the shower(s) location?		
All shower heads should be cleaned, disinfected and descaled atleast once every 6 months. Aerosol p	production should be minimised during this process.	
Identified Defect/Risk Recomm	nendations	2500
Recommendation of the second o	ienuations	
		1 3 4
RISK CATEGORY - Dead Legs & Redundant Pipework	Yes	No
Are there any dead legs in the property?		1
If Yes, identify location?		
Sections of pipework which are redundant owing to the system design and have little/no through flow of Any dead legs in pipework should be removed or the system altered so that water flows through all pipe.	of water (known as 'dead legs') can allow water to stagnate in the system	L
The state of the system are set of the system are set of the state of the system are set	ework on a regular basis.	
Identified Defect/Risk Recomm	endations	
RISK CATEGORY - Unoccupied Properties	Yes	No
Is the property left unoccupied for periods of time?		1
If Yes, are there arrangements in place to flush them through on atleast a weekly basis?		
During periods of unoccupancy all outlets on hot and cold water systems should be flushed through on	ce a week for atleast 2 minutes. For longer periods consider draining the	
system. Make sure that the system is flushed through when it is re-occupied by running all outlets for a Aerosol production should be minimised during this process.	minimum 2 minutes.	
Identified Defect/Risk Recomm	endations	18
ADVICE TO TENANTS		No
Has advice been given to the tenants as to the risks of Legionnaires Disease in a domestic	setting and their responsibilites to minimise risk?	
Advice Given/Action Required (list)	Completed:	
al it it is a sill		W 27
Advised tenent to closer bed shown has	1 en con GNall	
	0 110014	
The assessment is complete and should be reviewed regularly (at least once per year) and	d specifically when there is a reason to suspect it is no longer vi	alid.
You should ensure that the recommendations above are impleme	nted and any existing controls maintained.	

Received By:

Issued By:

Date: 30/05/10 6 Fignature:

JAMES VNICE

Date 10/9/19