


Your Test Certificate													<b>Property Details</b>  <b>6B Macewan Place</b> <b>Kilmarnock</b> <b>KA3 7ER</b>
<b>TEST DATE</b>		23 Mar 11		 <div> <b>info@Profurbish.net</b>  <b>08000 112 347</b>  <b>EPC's</b>  <b>PAT Testing</b>  <b>Commercial Cleaning</b> </div>									
<b>TEST EQUIPMENT</b>		Seaward Europa Plus											
<b>SERIAL NUMBER</b>		44A-1176											
<b>CALIBRATION DATE</b>		18 feb 2011											
				Visual Inspections				Test Readings		Functional Check	Next Test Due	Pass or Fail	Additional Comments / Observations
ID Tag	Brief Description of Item	Location of Item	Class	Fuse	Plug	Flex	Body	Earth Ω	Insulation MΩ				
													No items reported by the tenant as being left by the Landlord
<b>Results of Socket Continuity and Breakdown Resistance Test</b>													
<b>Test</b>				<b>PASS / FAIL</b>					<b>Comments</b>				
Socket Continuity and Breakdown Resistance Test				FAIL					See below				
<b>Comments</b>													
<p>Reverse polarity problem identified from twin socket in rear bedroom. Needs checked.</p> <p>Was not permitted access to one of the bedrooms.</p>													

