



CapitalVolt CapitalVolt Ltd electrical services Smoke Detection System Report

Details of client/person ordering ordering the work

Name: Cox&Co Edinburgh

Address: 12 Castle Terrace, Edinburgh, EH1 2DP

Installation address details

1 Kirk Loan Edinburgh Eh12 7HD

Extent and limitations of inspection

All detectors cleaned, test button pressed and expiry date noted.

Details of system

Location	Detector	Power	Expiry	Grade
Hall	Smoke	Mains	February 2026	D2
Lounge	Smoke	Mains	February 2026	D2
Kitchen	Heat	Mains	February 2026	D2

Summary of condition of the installation

Satisfactory

N.			
IIX I		ТΩ	0
IN	LW.		

N/A