



**PROPERTY
PROTECTION
GROUP**

PAT REPORT CERTIFICATE: INSTRUMENT NUMBER: 101414 398/1003-062

SITE ADDRESS: Flat 7, Pitfour Castle, Glencarse PH2 7NJ

Engineer: **Robbie Marshall**

Asset ID	Description	Location	Retest period (months)	Normal supply voltage (v)		Class: I, II, IT	Ext'n lead	IEC lead	Fuse rating (A)	Formal visual inspection		R Cont (Ω)	R INS (M Ω)	Leaking current (mA)	Polarity		Portable RCD		Retest date	Overall	
				110v	230v					PASS	FAIL				PASS	FAIL	PASS	FAIL		Pass	Fail
1	Hoover Washing Machine	Kitchen	12		✓	I			13	✓		0.13	>99.99	0.1	✓		N/A		4/3/22	✓	
2	Beko Fridge/Freezer	Kitchen	12		✓	I			13	✓		0.08	>99.99	0.12	✓		N/A		4/3/22	✓	
3	Genie Vacuum	Bedroom	12		✓	I			13	✓		0.14	>99.99	0.18	✓		N/A		4/3/22	✓	

Items tested in accordance with the IET Code of Practice for In-Service Inspection and Testing of Electrical Equipment

Comments:

Signature: 