

Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of

flues (Integrity, Constructions and Lining) has been carried out.

Certificate Reference

15 Bailie Dr 2019

Certificate No:1961

| Engineers Details | | | | | | Installation Details | | | | | | | Client Details | | | | | |
|---|---|---|---------|--|---------------|----------------------|------------------------|---------------------------------------|--|---------------------------------------|--|--|--|---|--|--------------------------------------|--------------------------------------|--|
| Trading Title | ng Title Westhill Boiler Services | | | | | allation lress | 15 Dail | io drivo | | | | Client Winchesters Le | | | _ | | | |
| Address | Westhi | 11 Hilltop Gardens Westhill Aberdeenshire | | | | Alford | | | ailie drive d | | | | | 22-24 South Mount Street Aberdeen | | | | |
| | Post Code: AB326PN | | | | | | Post Code: | | | | | | | F | Post Cod | e: AB25 | 52TB | |
| Gas Safe No | s Safe No: 553934 Telephone No: 07534934965 | | | Tele | Telephone No: | | | | | | Telephone No: | | | | | | | |
| Appliance | Details | | | | | Inspection Details | | | | | | | | • | | | | |
| Loc | ation | Appliance Type | Make | Model | CO2 Reading | CO Reading | FlueType (OF/RS/FL) | Appliance Inspected (YES/NO/NA) | Combustion Analysis Reading (CO/CO2) | Landlords Appliance (YES/NO/NA) | Operating Pressure(mbar) or Heat Input(KW) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA) | Flue Performance Test (PASS/FAIL/NA) | Appliance Serviced (YES/NO/NA) | Appliance Safe To Use (YES/NO) | |
| Kitchen | | Central heating | Ariston | Clas He System | 8.5 | 8 | RS | YES | 0.0001 | YES | 18.1 kw | YES | YES | YES | PASS | YES | YES | |
| Kitchen | | Hob | Smeg | 4 Burner | | | FL | YES | 0 | YES | 4.9 kw | YES | YES | N/A | N/A | YES | YES | |
| | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | |
| Faults/Not | Faults/Notes Remedial Work Taken | | | | | | | | | | | | | Warnir | ng Notic | e Fixed | | |
| 1 | | | | | | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | | | | |
| 4 | 4 | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | |
| Emergency Control Valve accessible: YES Gas Tightness Satisfactory: YES Signatures Report Issued By: | | | | | | | | | | | | |) Number: | 55393 | 4 | | | |
| Gas Installation Pinawork Visual Inspection Satisfactory | | | | | | | | | | | | | Date: | Wed-11-12-2019 | | | | |
| Number Of Appliances Tested: 2 Equipotential Bonding: YES Report Received By: | | | | | | | | | | | | | | | | | | |
| NEXT INSPECTOR BEFORE: CO Alarm fitted and working? | TION DUE | ON Thu-10-1 Smoke alarm fitted and working? | VEC | allation Pass: YES Gas Safety Report was created | • | me: | | | | | | | | Date: | Wed-1 | 1-12-2019 | | |