

Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of

flues (Integrity, Constructions and Lining) has been carried out.

Certificate Reference

Cas 14 1.1 Millview Cr17

Certificate No:Gas003487

Engineers Details							Installation Details						Client Details						
Trading Title	Gas Select Technical Services Ltd						allation dress	14 1/1 Millview Crescent							Castle Residential				
Address	4d Auchingramont Rd Hamilton						Johnston						Address 63 Causeyside Street Paisley						
	Post Code: ML3 6JT							Post Code: PA5 8QA							F	Post Cod	e: PA1	1YT	
Gas Safe No:	564145 Telephone N			No: 07917	07917468759		Telephone N					Telephone No:		01418895464					
Appliance D	etails								Inspec	tion Deta	ails								
Location		Appliance	Туре	Make	Model	CO2 Reading	CO Reading	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NA)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
Kitchen Cupboard Co		Combi boile	er ALF	НА	CD28C	9	65	RS	YES	0.001	YES	29 kw	YES	YES	NO	N/A	N/A	YES	
Kitchen		Hob	Hot	point	Unknown	Na	Na	FL	YES	Na	YES	5.4 kw	N/A	YES	N/A	N/A	N/A	YES	
Faults/Note	s		<u> </u>	Remedial Work Taken									Warning Notice Fixed						
1 Flue and Prv ncs Non fsd hob ncs																	NA		
2																			
3	3																		
4																			
5																			
Emergency Control Valve accessible: YES Gas Tightness Satisfactory: YES Report Issued By:														Gas ID Number:			4134706		
Gas Installation	Pipework	Visual Inspe	ction Satisfac	tory:	YES		. –	paul ferrie Signed: Date:							Thu-03-08-2017				
Number Of Appliances Tested: 2 Equipotential Bonding: YES Report Received By:																			
NEXT INSPECTION DUE ON OR BEFORE: CO Alarm fitted and working? YES Installation Pass: YES Name: Signed Signed YES This Gas Safety Report was created by Gas Checker Software 2016 all rights reserved www.gasche															Date:	Thu-03	3-08-2017		