

Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of

flues (Integrity, Constructions and Lining) has been carried out.

Certificate Reference

283 High Street

Certificate No:BD688

Engineers Details							Insta	Illation D	etails			Client Details								
Trading Title	BR Ga	BR Gas Services and Maintenance Ltd						allation dress	202 High Chroat					Client Addres		Fife Letting Service Ltd(Cowdenbeath)				
Address		School Street wdenbeath						Address		283 High Street Methil Fife				Addies	1000	3 School Street Cowdenbeath Fife				
	Post Code: KY4 8LT									Post Code: KY83ED					Post Code: KY48LT					
Gas Safe No						Te	ephone N	o:					Telephone No: 01383515			830				
Appliance	Details									Inspec	tion Det	ails								
Location		Appliance Type		Make		Model	CO2 Reading	CO Reading	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NA)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1 Kitchen	Combi bo		r Vokera			Compact 24	4.9	12	RS	YES	0.0003	YES	10 mbar	YES	YES	YES	PASS	YES	YES	
2 Kitchen		Hob		Unbranded		Unknown	Na	Na	N/A	YES	Na	YES	Na mbar	N/A	YES	N/A	N/A	N/A	YES	
3																				
4																				
5																				
Faults/Not	es							Remedial Work Taken									Warning Notice Fixed			
1 No ffd on hob																		NA		
2																				
3																				
4																				
5																				
Emergency Caccessible:	ontrol Valve	Y	ES G	ias Tightn	ess Sati	sfactory: YES		Signatures Report Issued By: Gas ID Number:									36786	3678696		
Gas Installation Pipework Visual Inspection Satisfactory: YES Name: Brian Dewar												Signe	d: Ú S	.00		Date:	Thu-06	6-06-2019		
Number Of Appliances Tested: 2 Equipotential Bonding: YES Report Received By:																				
NEXT INSPECTOR BEFORE: CO Alarm fitted and working?	NEXT INSPECTION DUE ON Fri-05-06-2020 Installation Pass: YES Name: Signed: Date:												Thu-06	6-06-2019						